

Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C. Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination
	6 (b) Defects requiring corrective action as soon as reasonably practicable.		
01	General Play Area	General Play Area	
80450197/19	(a) None. (b) None.	It is recommended that signage is fitted displaying the following information: Name of the playground Contact details to report accidents or damage Location of the nearest telephone (Not essential) Age Restrictions Prohibition of Wheeled Play Equipment Other relevant local information where applicable. We recommend a secondary access gate should be fitted.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor

Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

	Comments H	istory	
- 4	Date/Time	User	Comment

Report forwarding History						
Date Requested	Date emailed	Sender	Recipients	Comments		



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C. Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.			
02	Seesaw Record	General Play Area	Record	
80420197/19	(a) None. (b) None.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor

Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H	istory	
Date/Time	User	Comment

Report forwarding History						
Date Requested	Date emailed	Sender	Recipients	Comments		



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.			
03 Set of Two Swings - Cradle Seats Record		General Play Area	Record	
80400197/19	(a) None. (b) The frame is showing signs of corrosion and should be descaled and repainted.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor

Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History					
Date/Time	User	Comment			

Report forwarding History						
Date Requested	Date emailed	Sender	Recipients	Comments		



Date: 23/08/2023

## REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C. Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	on before further 7. Other observations. If none, state 'none'.	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.		
04	Spring Mobile - Horse	General Play Area	
80430197/19	(a) None. (b) None.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor Contact: Ian Hallam Telephone: 07875 888502

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H		
Date/Time	User	Comment

Réport forwarding History						
Date Requested	Date emailed	Sender	Recipients	Comments		



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C. Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.			
Set of Two Swings - Flat Seats Wicksteed		General Play Area	Wicksteed	
80410197/19	(a) None. (b) None.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: lan Hallam Designation: Engineer Surveyor Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus. Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H	istory	
Date/Time	User	Comment

Report forwarding History					
Date Requested	Date emailed	Sender	Recipients	Comments	



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.			
06	Multi Activity Units (playgrounds) 2 - 5 activities	General Play Area		
80440197/19	(a) None. (b) None.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor

Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H	istory	
Date/Time	User	Comment

Report forwarding History					
Date Requested	Date emailed	Sender	Recipients	Comments	



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C. Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
5. Report No.	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.		and the second s	
07	Playground Equipment:- Steel Bench 1	General Play Area		
90233114/6	(a) None. (b) None.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/202

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H	istory	
Date/Time	User	Comment

Report forwarding History					
Date Requested Date emailed Sender Recipients Comments					



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer	
6 (a) Defects which require action before fu use or before a specified date.		7. Other observations. If none, state 'none'.		
	6 (b) Defects requiring corrective action as soon as reasonably practicable.		Adulturarious palacierani et di socia ana pinno et est est esta anno anno anno anti-	
08	Playground Equipment:- Steel Bench 2	General Play Area		
90243114/6	(a) None. (b) None.	None.	23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor Contact: Ian Hallam Telephone: 07875 888502 Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments H	istory	
Date/Time	User	Comment

Report forwarding History					
Date Requested	Date emailed	Sender	Recipients	Comments	



Policy / Contract No: QLA10H0830083000 Schedule: L0068

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: BUTTERCUP AVENUE PLAY AREA BUTTERCUP AVENUE DONNISTHORPE LE67 1

1. ES Item No	2. Item Description			
5. Report No.	The state of the s	3. Situation	4. Manufacturer	
	6 (a) Defects which require action before further use or before a specified date.	7. Other observations. If none, state 'none'.	te 8.Date of Examination	
	6 (b) Defects requiring corrective action as soon as reasonably practicable.			
09	Playground Equipment:- Steel Refuse Bin	General Play Area		
00253114/6	(a) None.	The state of the s		
	(b) The steel bin is showing signs of corrosion and should be descaled and repainted.  examined in accordance with the requirements of BSEN1 defect likely to affect its' continued safe usage. The above		23/08/2023	

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was The equipment has been examined in accordance with the requirements of BSEN11/b Part / section b(∠)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam Designation: Engineer Surveyor

Contact: Ian Hallam Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments F	History		
Date/Time	User	Comment	

Report forward	photography and the second				إستندند
Date Requested	Date emailed	Sender	Recipients	Comments	