

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 **Schedule:** L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
01	General Play Area	General Play area	
80490197/19	(a) None. (b) None.	It is recommended that signage is fitted displaying the following information: Name of the playground Contact details to report accidents or damage Location of the nearest telephone (Not essential) Age Restrictions Prohibition of Wheeled Play Equipment Other relevant local information where applicable. We recommend a secondary access gate should be fitted.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 Schedule: L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
03	Spring Mobile - Grey and Pink	General Play area	
80470197/19	(a) Sections of the impact attenuating surface have reduced in surface area causing a tripping hazard and should be restored to the original surface area on or before 23/09/2023. (b) Some plastic bolt covers are missing and should be replaced. The spring is showing signs of corrosion and should be descaled and repainted.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments



ZURICH

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 Schedule: L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
02	Spring Mobile - Blue and Red	General Play area	
80480197/19	(a) None. (b) The spring is showing signs of corrosion and should be descaled and repainted.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 Schedule: L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
05	Playground Equipment:- Steel Bench 1 (front)	General Play area	
90333114/6	(a) None. (b) None.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

.. [more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 **Schedule:** L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
05	Playground Equipment:- Steel Bench 1 (front)	General Play area	
90333114/6	(a) None. (b) None.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 **Schedule:** L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
06	Playground Equipment:- Steel Bench 2 (centre)	General Play area	
90343114/6	(a) None. (b) None.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments

REPORT OF EXAMINATION OF PLAY EQUIPMENT

Policy / Contract No: QLA10H0830083000 **Schedule:** L0072

Policy / Contract Name: NORTH WEST LEICESTERSHIRE D. C.

Name of Occupier: NORTH WEST LEICESTERSHIRE D. C.

Address: DAWKINS ROAD PLAY AREA DAWKINS ROAD DONNISTHORPE LE67 1

1. ES Item No	2. Item Description	3. Situation	4. Manufacturer
5. Report No.	6 (a) Defects which require action before further use or before a specified date. 6 (b) Defects requiring corrective action as soon as reasonably practicable.	7. Other observations. If none, state 'none'.	8. Date of Examination
07	Playground Equipment:- Steel Bench 3 (rear)	General Play area	
90353114/6	(a) None. (b) None.	None.	23/08/2023

The equipment has been examined in accordance with the requirements of BSEN1176 Part 7 section 6(2)c and unless otherwise indicated was found to be free from any defect likely to affect its' continued safe usage. The above item was not in any way dismantled for the purpose of the examination but where it is considered that such action will be necessary for further examination, this is indicated in the report Observations

Authenticated by: Ian Hallam
Designation: Engineer Surveyor

Contact: Ian Hallam
Telephone: 07875 888502

Date: 23/08/2023

Zurich Engineering, Floor 6, The Colmore Building, 20 Colmore Circus, Queensway, Birmingham, B4 6AT. Telephone: 0121 697 9260 Fax: 0121 697 9136 Email: engineering@uk.zurich.com
Zurich Management Services Limited. Registered in England and Wales No. 2741053. Registered Office: The Zurich Centre, 3000 Parkway, Whiteley, Fareham, Hampshire PO15 7JZ.

Comments History		
Date/Time	User	Comment

[.. more comments](#)

Report forwarding History				
Date Requested	Date emailed	Sender	Recipients	Comments